Change Notice Form

Change Notice # PCN 064	Date of Notice 2/21/2022	Distribution: ☒ General ☐ Customer Specific Post Change Notice to Website? ☒ yes ☐ no

Title:End of Life for FFT-10A Free Topology Twisted Pair Transceiver model 50051R

Products Affected: See Appendix I for a list of complete part numbers.

Change Type:
☐ Document only ☐ Mat'l/Composition ☐ Manufacturing Process
☐ Manufacturing Location ☐ Quality/Reliability ☐ Logistics ☐ Design
☒ EOL/Product Discontinuance ☐ Other

Qualification Report Available:	Click here to enter a date.	☒ not applicable
Product Sample:	Click here to enter a date.	☒ not applicable
Target Production Release:	Click here to enter a date.	

Last Time Buy:	2/25/2022	☐ not applicable
Last Time Ship Date:	8/26/2022	☐ not applicable

Sites Affected:	☒ None	Description:
Impact on Quality and Reliability	☒ None	Description:
Traceability of Change	☒ not applicable ☐ Product Mark ☐ Date Code	
	☐ Lot number traceability	

This change affects datasheet, form, fit, function or reliability of the product			
	☐ Yes	☐ No	☒ Not Applicable

Description of Change:
 End of Life for FFT-10A Free Topology Twisted Pair Transciever.

The FFT-10A Free Topology Twisted Pair Transceiver model 50051R has moved to End of Life.
We have been notified by our supplier that they can no longer supply wafers for this product.
We have limited supply for last time buy and may not be able to fulfill all orders.
If customer need product, please contact Renesas Sales immediately to discuss needs

Should you have any questions, please contact your local Renesas sales office or authorized distributor.

Renesas will deem this change accepted, unless specific written conditions of acceptance are provided by the customer, within 30 days from the date of this notice. Renesas reserves the right to ship either the original version or the new version of the affected product after the Target Production Release Date specified in this notice.

APPENDIX I Affected Products
FFT-10A Free Topology Twsisted Pair Tranciever model 50051R - No replacement