

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.			
Parts Affected :			
Part No.	Package	Part No.	Package
MBR1040CT-HF	TO-220AB	MBRF10100CT-HF	ITO-220AB
MBR1060CT-HF	TO-220AB	MBRF10150CT-HF	ITO-220AB
MBR2040CT-HF	TO-220AB	MBRF10200CT-HF	ITO-220AB
MBR2060CT-HF	TO-220AB	MBRF1040CT-HF	ITO-220AB
MBR3040CT-HF	TO-220AB	MBRF1060CT-HF	ITO-220AB
MBR3060CT-HF	TO-220AB	MBRF20100CT-HF	ITO-220AB
MBR10100CT-HF	TO-220AB	MBRF20150CT-HF	ITO-220AB
MBR10150CT-HF	TO-220AB	MBRF20200CT-HF	ITO-220AB
MBR10200CT-HF	TO-220AB	MBRF2040CT-HF	ITO-220AB
MBR20100CT-HF	TO-220AB	MBRF2060CT-HF	ITO-220AB
MBR20150CT-HF	TO-220AB	MBRF3040CT-HF	ITO-220AB
MBR20200CT-HF	TO-220AB	MBRF3060CT-HF	ITO-220AB
SR1030-G Thru. SR10200-G			TO-220AC
Reason for Discontinuance :			
Due to the wafer supplier has suddenly shut down, the part listed will be discontinued.			
Alternative Products :			
Please contact sales person or manufacturer's representative.			
Effective Date : Feb 23, 2021			
R&D Dept. Signature :		QA Dept. Signature :	
			