

PCN Number:	20130916002		PCN Date:	09/18/2013
Title:	TPS54260-Q1 datasheet - CMS C1308093			
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037	Dept: Quality Services
Change Type:				
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process	<input type="checkbox"/>
<input type="checkbox"/>	Design	<input checked="" type="checkbox"/>	Electrical Specification	<input type="checkbox"/>
<input type="checkbox"/>	Test Site	<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material	<input type="checkbox"/>
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials	<input type="checkbox"/>
		<input type="checkbox"/>	Part number change	
PCN Details				
Description of Change:				
Texas instruments publication SLVSAH8D has changed as described below: Page 24 - Changed PWRGD from 10 kΩ to 1 kΩ in <i>Power Good (PWRGD Pin)</i> section				
Reason for Change:				
Correct typographical error.				
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):				
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.				
Changes to product identification resulting from this PCN:				
None				
Product Affected:				
TPS54260QDGQRQ1				

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com