



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000963

DATE: 03-Apr-2019

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|--------------|-------------------|-------------------------|-----------------|--------------------|----------------------------------------------|
| Reactivation | DG418LDY+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | DS1124U-25+ | N/A | | | Part reactivated from prior notice: M000870 |
| Reactivation | DS1124U-25+T | N/A | | | Part reactivated from prior notice: M000870 |
| Reactivation | DS1809Z-050+ | N/A | | | Part reactivated from prior notice: M000872 |
| Reactivation | DS1922L-F5#A22 | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | DS3881E+T&R/C | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | DS3882E+C | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX1098CEAE+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX1182ECM+TD | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX1185ECM+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX1301BEUP+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX13055EETI+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX13362ATL+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX1446GHJ+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16838AUP+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16903SATB33+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX16903SATB33+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16907RAUE+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX16907RAUE+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16909RATE+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX16909RATE+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16910DASA9+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16910DASA9+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16910DATA9+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16910DATA9+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16945TGUT+ | N/A | | | Part reactivated from prior notice: M000963I |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-May-2019

| | | | | | |
|--------------|-------------------|-----|--|--|----------------------------------------------|
| Reactivation | MAX16993AGJB/VY+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX16993AGJB/VY+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX1976AETT150+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX1976AETT180+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX2171ETL+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX2180AETG+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX2180AETG+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX2680AUT+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX3318EEUP+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX3379EEUD+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX3393EEUD+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX4020EEE+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX4522ESE+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX4548EAX+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX4590EWE+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX4695EGC+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX4835ETT25BD2+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX4837ETT33BD3+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX4907ELA+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX5027EUT+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX5063AASA+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX539ACSA+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX541AESA+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX5489EUD+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX5661GCB+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6138BEXR41+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6174BASA+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6316LUK31BX+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6316LUK31BX+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6319LHUK31A+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6381XR23D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6382XR26D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6383XR29D1+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6383XR31D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6385XS29D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6390XS30D4+ | N/A | | | Part reactivated from prior notice: M000962I |

| | | | | | |
|----------------|------------------|-----|-------------|-------------|----------------------------------------------|
| Reactivation | MAX6390XS30D7+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6390XS44D4+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6394US480D1+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX6412UK26+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6418UK31+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6423XS29+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6467XS32D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6706LKA+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6750KA30+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6776XKA+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6791TPSD2+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6834HXR2+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6856UK23D3+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX6970AUE+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX7375AXR425+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX803LEXR+T10 | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX809LEUR+T10 | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX8878EUK30+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX8878EUK50+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX8891EXK89+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX8896EREE+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX9247GCM+T | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX9250ECM+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX9395EHJ+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX9532AUB/V+ | N/A | | | Part reactivated from prior notice: M000963I |
| Reactivation | MAX9532AUB/V+T | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MAX9650AZK+ | N/A | | | Part reactivated from prior notice: M000962I |
| Reactivation | MX7847AR+T | N/A | | | Part reactivated from prior notice: M000963I |
| Discontinuance | DS1089LU-22F+T | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | DS1089LU-A29+T | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | DS1805E-010+ | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | DS1805Z-010+T&R | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | DS1844E-050+T&R | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | DS4301U-200+T&R | N/A | 03-Apr-2019 | 03-Apr-2019 | Part can no longer be manufactured |
| Discontinuance | MAX14709ENL+CNV | N/A | 02-Apr-2020 | 02-Oct-2020 | The part was not released |
| Discontinuance | MAX14709ENL+TCNV | N/A | 02-Apr-2020 | 02-Oct-2020 | The part was not released |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-May-2019

| | | | | | |
|----------------|---------------------|--------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX20723EPE+ | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20723EPE+T | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20724EPE+ | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20724EPE+T | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20726EPE+ | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20726EPE+T | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20727EPE+ | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX20727EPE+T | N/A | 03-Apr-2019 | 03-Apr-2019 | The part was not released |
| Discontinuance | MAX44000EVKIT# | N/A | 03-Apr-2019 | 03-Apr-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX44000GDT+ | N/A | 03-Sep-2019 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX44000GDT+T | N/A | 03-Sep-2019 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX44000PMB1# | MAX3750CEE+T | 03-Apr-2019 | 03-Apr-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX9132EVKIT+ | N/A | 03-Apr-2019 | 03-Apr-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX9132GUP+ | N/A | 02-Apr-2020 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX9132GUP+T | N/A | 02-Apr-2020 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX9134GHJ+ | N/A | 02-Apr-2020 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX9135GHJ+ | N/A | 02-Apr-2020 | 02-Oct-2020 | Part can no longer be manufactured |
| Discontinuance | MAX96911DCOAXEVKIT# | N/A | 03-Apr-2019 | 03-Apr-2019 | EVKIT is No Longer Supported |