

Doc. No. : PDN220603  
Date : Jun 29, 2022

To : Dear Valued Customers

**Product Discontinuance Notice**

Subject : DFS, DBS package products discontinue.							
Parts Affected :							
<table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">Part No.</th> <th style="padding: 5px;">Package Type</th> </tr> </thead> <tbody> <tr> <td style="padding: 5px;">DB101S-G Thru. DB107S-G</td> <td style="padding: 5px;">DBS</td> </tr> <tr> <td style="padding: 5px;">DF005S-G Thru. DF10S-G</td> <td style="padding: 5px;">DFS</td> </tr> </tbody> </table>		Part No.	Package Type	DB101S-G Thru. DB107S-G	DBS	DF005S-G Thru. DF10S-G	DFS
Part No.	Package Type						
DB101S-G Thru. DB107S-G	DBS						
DF005S-G Thru. DF10S-G	DFS						
Reason for Discontinuance :							
Follow the international halogen-free specification, meet the EU Halogen Free and RoHS requirements.							
Alternative Products :							
<table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">EOL p/n.</th> <th style="padding: 5px;">Alternative p/n.</th> </tr> </thead> <tbody> <tr> <td style="padding: 5px;">DB101S-G Thru. DB107S-G</td> <td style="padding: 5px;">DB101S-HF Thru. DB107S-HF</td> </tr> <tr> <td style="padding: 5px;">DF005S-G Thru. DF10S-G</td> <td style="padding: 5px;">DF005S-HF Thru. DF10S-HF</td> </tr> </tbody> </table>		EOL p/n.	Alternative p/n.	DB101S-G Thru. DB107S-G	DB101S-HF Thru. DB107S-HF	DF005S-G Thru. DF10S-G	DF005S-HF Thru. DF10S-HF
EOL p/n.	Alternative p/n.						
DB101S-G Thru. DB107S-G	DB101S-HF Thru. DB107S-HF						
DF005S-G Thru. DF10S-G	DF005S-HF Thru. DF10S-HF						
Last time buy : Sep 30, 2022							
Effective Date : Dec 30, 2022							
R&D Dept. Signature :	QA Dept. Signature :						
							