

MKT_NO	NOTICE_TYPE	ISSU_DATE	LAST_ORDER_DATE	LAST_SHIP_DATE	REASON	RECOMMENDED_REPLACEMENT
73M1916-IMR/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-68IMR/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1210F-44M/F/PB	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1215F-44M/F/PD	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1215F-44M/F/PG	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S8009C-20IMR/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73M1902-IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73M1912-IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73M1916-IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-44IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-44M/F/PD	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-68IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-68M/F/P1	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1215F-68M/F/PB	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1217F-68M/F/PE	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S8009C-20IM/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX2906ETL+TW	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX2906ETL/V+W	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5875EGK+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5883EGM+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5884EGM+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5885EGM+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5887EGK	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5887EGK+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
MAX5889EGK+	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A
73S1209F-44IMR/F	Discontinuance	10/2/2015 12:00	4/1/2016 12:00	10/1/2017 12:00	Part can no longer be manufactured	N/A