

Product Discontinuing Notification

1. PDN No.:	<i>PDN18001</i>
2. To:	<i>All Involved Customers</i>
3. Contact Team:	<i>PM – Chris Lin HQ QRA – Patty Wu (Act.)</i>
4. Issue date:	<i>2018/3/8</i>
5. Affected product/ product family:	6. Recommended replacement:
<i>Please see attached Involved P/N List</i>	<i>Please see attached Involved P/N List</i>
7. Reason for discontinuing:	
<ul style="list-style-type: none"> <i>1. Low & No demand</i> <i>2. Production constraint</i> 	
8. Last time buy/ order entry:	<i>2018/6/8</i>
9. Last shipment date:	<i>2018/9/10</i>
10. Please let us know if you have any question/ comment:	
11. Customer feedback required latest: (should we receive no feedback, the change will be deemed as accepted!)	<i>2018/4/23</i>
12. Approved by:	<i>Angelito Baes</i>

Family	Package	TSC P/N	New TSC P/N
AC-DC LED Lighting IC	SOP-8	TS19751BCS RLG	TS19751ACS RLG
N-Channel	ITO-220	TSM13N50ACI C0G	None
N-Channel	ITO-220	TSM4N70CI C0G	None
N-Channel	ITO-220	TSM4NC60CI C0G	TSM4NB60CI C0G
N-Channel	ITO-220	TSM6NB60CI C0G	TSM7NC60CF C0G
N-Channel	ITO-220	TSM7N65ACI C0G	TSM7NC65CF C0G
N-Channel	ITO-220	TSM8N70CI C0	None
N-Channel	ITO-220	TSM8N70CI C0G	None
N-Channel	PDFN56	TSM052N06PQ56 RLG	TSM045NB06CR RLG
N-Channel	PDFN56	TSM120N10PQ56 RLG	TSM160N10LCR RLG
N-Channel	SOT-223	TSM1N45CW RFG	None
N-Channel	SOT-23	TSM3404CX RFG	TSM240N03CX RFG
N-Channel	TO-220	TSM13N50ACZ C0G	None
N-Channel	TO-220	TSM210N06CZ C0G	None
N-Channel	TO-220	TSM4NB60CZ C0G	None
N-Channel	TO-220	TSM6NB60CZ C0G	None
N-Channel	TO-251 (I-PAK)	TSM4N70CH C5G	None
N-Channel	TO-251 (I-PAK)	TSM6N50CH C5G	None
N-Channel	TO-251 (I-PAK)	TSM6N60CH C5G	None
N-Channel	TO-251 (I-PAK)	TSM8N50CH C5G	None
N-Channel	TO-251S (I-PAK SL)	TSM2NB65CH X0G	None
N-Channel	TO-252 (D-PAK)	TSM10N06CP ROG	TSM900N06CP ROG TSM340N06CP ROG
N-Channel	TO-252 (D-PAK)	TSM2NB65CP ROG	None
N-Channel	TO-252 (D-PAK)	TSM4N70CP ROG	None
N-Channel	TO-252 (D-PAK)	TSM500N03CP ROG	None
N-Channel	TO-252 (D-PAK)	TSM6N50CP ROG	None
N-Channel	TO-252 (D-PAK)	TSM6N60CP ROG	None
N-Channel	TO-252 (D-PAK)	TSM8N50CP ROG	None
N-Channel	TO-92	TSM1N45CT A3G	None
N-Channel	TO-92	TSM1N45CT B0G	None
N-Channel	TO-92	TSM1NB60SCT A3	None
N-Channel	TO-92	TSM1NB60SCT A3G	None
N-Channel	TO-92	TSM1NB60SCT B0	None
N-Channel	TO-92	TSM1NB60SCT B0G	None
NPN Bipolar Transistor	TO-92	TSC5988CT A3G	None
NPN Bipolar Transistor	TO-92	TSC5988CT B0G	None
NPN Bipolar Transistor	TO-92	TSC873CT A3G	None
NPN Bipolar Transistor	TO-92	TSC873CT B0G	None
NPN Bipolar Transistor	TO-92	TSC966CT A3G	None
NPN Bipolar Transistor	TO-92	TSC966CT B0G	None
P-Channel	SOP-8	TSM4425CS RLG	TSM085P03CS RLG
P-Channel	SOP-8	TSM4435BCS RLG	TSM085P03CS RLG
P-Channel	SOP-8	TSM4459CS RLG	TSM085P03CS RLG
P-Channel	SOT-23	TSM2301BCX RFG	TSM650P02CX RFG
PNP Bipolar Transistor	TO-92	TSA894CT A3	None
PNP Bipolar Transistor	TO-92	TSA894CT B0	None
Reset IC	SOT-23	TS3809CXA RFG	None
Reset IC	SOT-23	TS3809CXB RFG	None
Reset IC	SOT-23	TS3809CXC RFG	None
Reset IC	SOT-23	TS3809CXG RFG	None
Reset IC	SOT-23	TS3810CXA RFG	None
Reset IC	SOT-23	TS3810CXB RFG	None
Reset IC	SOT-23	TS3810CXC RFG	None
Reset IC	SOT-23	TS3810CXD RFG	None
Reset IC	SOT-23	TS3810CXE RFG	None
Reset IC	SOT-23	TS3810CXF RFG	None
Reset IC	SOT-23	TS3810CXG RFG	None

Standard Linear Voltage	TO-92	TS78L03CT A3G	None
Standard Linear Voltage	TO-92	TS78L03CT B0G	None
Standard Linear Voltage	TO-92	TS78L05CT A3G	None
Standard Linear Voltage	TO-92	TS78L05CT B0G	None
Standard Linear Voltage	TO-92	TS78L09CT A3G	None
Standard Linear Voltage	TO-92	TS78L09CT B0G	None
Standard Linear Voltage	TO-92	TS78L12CT A3G	None
Standard Linear Voltage	TO-92	TS78L12CT B0G	None
Standard Linear Voltage	TO-92	TS78L15CT A3G	None
Standard Linear Voltage	TO-92	TS78L15CT B0G	None
Standard Linear Voltage	TO-92	TS79L05CT A3G	None
Standard Linear Voltage	TO-92	TS79L05CT B0G	None
Standard Linear Voltage	TO-92	TS79L09CT A3G	None
Standard Linear Voltage	TO-92	TS79L09CT B0G	None