

## **Product Change Notification (PCN)**

PCN Number	511285	Date Issued	December 28, 2021
Reason for Change	Equipment Transfer, Production Transfer or Rearrangement		
Change Type Description	This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.		
Reason for Short Notice	Special Request		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	March 28, 2022		
Sample Availability Date (Changed Part)	March 28, 2022		
Planned Implementation Date	April 30, 2022		
Method of Identifying Change Before Change	Date code	SFF	
	After cha		
Production plant location change Current After change	Change overview :     To better serve our customers and to leverage our global manufacturing footprint, Molex will relocate		
Manufacturing location Molex Shizouka Molex Vietnam	The trans		complete in 2022. Buffer stock and capacity tooling
Product Current No change		ilt as need to ensure a seamless transfe	er.
Machine/Tooling Current No change		t to form, fit and function.	
Man Current Change	No chang	e in product specification.	
Control plan Current No change	202396- 501568-0 • Qualificati For 1 <sup>st</sup> tot Molex will number o	ber impacted : 06**~15**, 203558-06**~15**, 203558 06**~15** ion report and samples : Available as ex ion : of production starting by Vietnam plant, I add "P" at the end of Traceability in the label as signal to recognize produ by Vietnam.	ecution plan.

## **molex**<sup>®</sup>

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:511285**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #
511285	2023960607
511285	2023960807
511285	2023960907
511285	2023961007
511285	2035580807
511285	5015680607
511285	5015680807
511285	5015681007
511285	5015681107
511285	5015681307

## Affected Parts:

202396-0607
203559-1507
501568-0707
501568-0907
501568-1207
501568-1307
501568-1407