

**Issue Date:** July 26<sup>th</sup>, 2019

Dear Valued Customer,

This notice is to inform you of a correction to a Product Change Notice (PCN) previously distributed by Littelfuse.

**Description of the Change:**

- We previously announced in PCN C0239 our intent to move the production site of select products.
- PCN C0239 incorrectly contained the attached subset of parts which are not changing manufacturing process, site, or supply chain.

**Reason for The Change:**

- This notification serves as a supplement to our prior PCN, correcting the extent of our site change.
- The inclusion of these part numbers on the prior PCN was exclusively a transposition error.

**Effective Date of the Change:**

- This PCN is retroactive to the distribution of PCN C0239, July 5<sup>th</sup>, 2019.

**What You Need to Do:**

- Any previous efforts to modify any manufacturing data of the above parts should cease immediately.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zacke Naughton  
Global Product Manager  
Littelfuse Commercial Vehicle Products



Michael DiCola  
Associate Product Manager  
Littelfuse Commercial Vehicle Products

**Part Numbers with no change (incorrectly included in C0239):**

178.6152.0042  
178.6152.0022  
178.7036.0002  
178.6152.2501  
178.7017.0001  
178.6105.1002  
177.5721.0001  
177.5702.0001  
177.5731.0001  
177.5705.0001  
177.5701.0001  
02981001ZXSS  
878-572  
178.7100.0001  
178.6764.0001  
178.6164.0001  
178.6164.0002  
178.6165.0002  
178.6165.0001  
178.7130.0002  
178.7115.0002  
178.4265.0002  
178.6105.0001  
178.6152.0001  
178.6115.0001  
178.6125.0001  
178.6192.0001  
178.6191.0001  
178.6150.0001  
178.4205.0002  
178.6105.0002  
178.7010.0000  
178.7012.4500  
178.6115.0002  
178.4215.0002  
178.6152.0002  
178.6150.0002  
178.6125.0002  
178.6116.4042