







New Products

In the News

eCOM

Summary

Effective February 16, 2013, Honeywell Sensing and Control changed the mating connector parts used with its CSCA-A Series Open Loop Current Sensors. The original mating connector parts to the Molex connector SD-5045 (terminal 0870-0056, housing 2201-1044) were made obsolete by the supplier. This change does not affect form, fit or function of the product.

	Obsolete Mating Connector Parts	New Mating Connector Parts
Terminal	<p>0870-0056</p> 	<p>50802-8000</p> 
Housing	<p>2201-1044</p> 	<p>51191-0400</p> 

Affected Listings

- | | | |
|--------------------|----------------------|--------------------|
| CSCA0050A000B15B01 | CSCA-A Series | CSCA0100A000B15B01 |
| CSCA0200A000B15B01 | | CSCA0300A000B15B01 |
| CSCA0400A000B15B01 | | CSCA0500A000B15B01 |
| CSCA0600A000B15B01 | | |

Action

Please communicate this information to your customers

Additional Materials

[Customer Letter](#) you can send to your customers

[Customer List](#)

Contact Information

North America: Rob Hillman, rob.hillmann@honeywell.com +1 763 954 4079

EMEA : Loic Moreau loic.moreau@honeywell.com, +41 78 721 15 06

A-P: Ray Jin, ray.jin@honeywell.com+86 (21) 2219 6472

Copyright © 2013 Honeywell International Inc. All rights reserved.

<p>Main Menu</p> <ul style="list-style-type: none"> Announcements Calendar Newsletters Profile 	<p>Quick Links</p> <ul style="list-style-type: none"> eCOM Portal Information Sample Portal Literature Warehouse Registration Literature Warehouse 	<p>Resources</p> <ul style="list-style-type: none"> Product Information Toolkit Marketing and Communications Toolkit Sales Toolkit Order Management
---	---	--