

January 17, 2019

Issue Number: 962

3M Intra-Connector Discontinuation

To Our 3M Authorized Distributors,

Due to low recent demand in combination with manufacturing tooling that is no longer capable of producing an acceptable product offering, 3M is discontinuing the Intra-Connector.

What is being discontinued?

1. The products noted in the below table are being discontinued. No additional production of these offerings will be offered as the tooling is no longer capable of producing an acceptable product offering.
2. There is limited inventory available for the highlighted SKUs and these products will be offered until the inventory is depleted.
3. All other remaining SKUs will be discontinued immediately.

3M ID#	SAP ID#	Product Description
80610353056	7010398305	922576-20-I=20-CONTACTINTRA-CONNECTOR
80610353072	7010320203	922576-26-I=26-CONTACTINTRA-CONNECTOR
80610353098	7010396276	922576-34-I=34-CONTACTINTRA-CONNECTOR
80610353114	7010348607	922576-40-I=40-CONTACTINTRA-CONNECTOR
80610353130	7010305556	922576-50-I=50-CONTACTINTRA-CONNECTOR
80610353155		922576-60-I=60-CONTACTINTRA-CONNECTOR

What actions and impact will this change have on purchase orders?

Upon depletion of the limited inventory, these SKUs will be deactivated for this family of connectors.

What do I need to do?

Please assess if you have any requirements for those SKUs with limited inventory and if required, contact 3M to determine how many units may still be available. Please update your listing of 3M products by removing all of the deactivated SKUs.

Please act now to:

- Advise your sales and technical staff

- Update your website and systems as appropriate by removing the deactivated SKUs.

If you have questions relating to this notice please contact your 3M representative who will be pleased to help you; or visit our website at [3M.com/Interconnect](https://www.3m.com/Interconnect).

Thank you for your understanding and continued partnership with 3M.

Mike Giesler
Global Business Manager
3M Electronics Materials Solutions Division