




 Search ...

PRODUCTS | APPLICATIONS | DESIGN SUPPORT | TRAINING | SAMPLE AND BUY | ABOUT
US | CONTACT US | myMicrochip Login

Product Change Notification - SYST-05IZTP612

Date:	06 Jan 2017
Product Category:	USB to Ethernet Controllers
Affected CPNs:	 
Notification subject:	Data Sheet - LAN950x USB 2.0 to 10/100 Ethernet Controller Data Sheet Data Sheet Document Revision
Notification text:	SYST-05IZTP612

Microchip has released a new DeviceDoc for the LAN950x USB 2.0 to 10/100 Ethernet Controller Data Sheet of devices. If you are using one of these devices please read the document located at [LAN950x USB 2.0 to 10/100 Ethernet Controller Data Sheet](#).

Notification Status: Final

Description of Change:

- 1) Updated sales listing and cover pages and minor text changes throughout.
- 2) In Section 8.2, Operating Conditions, XI Absolute Maximum input voltage level updated (+4.6V for LAN9500/LAN9500i, VDDCORE for LAN9500A/LAN9500Ai).
- 3) Updated Table 8-12, I/O Buffer Characteristics, XI Minimum Input High level updated (+1.4V for LAN9500/LAN9500i, +0.8V for LAN9500A/LAN9500Ai).

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 06 Jan 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [LAN950x USB 2.0 to 10/100 Ethernet Controller Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



Products | Applications | Design Support | Training | Sample and Buy | About Us |
Contact Us | Legal | Investors | Careers | Support

©Copyright 1998-2017 Microchip Technology Inc. All rights reserved. Shanghai ICP
Recordal No.09049794

Affected Catalog Part Numbers (CPN)

LAN9500I-ABZJ-TR
LAN9500I-ABZJ
LAN9500-ABZJ-TR
LAN9500-ABZJ-A00
LAN9500-ABZJ
LAN9500AI-ABZJ-TR-SEU
LAN9500AI-ABZJ-TR
LAN9500AI-ABZJ
LAN9500A-ABZJ-TR
LAN9500A-ABZJ